Lie seamon in in in	25X1A	WFO	accerning Child on a common. I have a history of the color or the nature basing	Mary Louis Common Services (1997) Annual Common Services (1997) Annual Common Services (1997)	and the state of t				3298	e Perfect to the control of the cont
MST	TOR: 2243Z 16 NO	V 64	:	SR PA PB	1	R		IN 5	7871	
ACTION	пож				KB WC DB B	Total Control of the	ROUTINE			A CONTRACTOR OF THE CONTRACTOR
FROM	25X1	Α		RP M	// //	8			age en les autres controles for agent partirelles la cont (1988) agent partirelles la cont (1988)	
TTS	DIRECTOR	The second secon		EDD RS(	) N		and the second section of the section o	24	প্রকাশ করে সাক্ষর করিব করে বিশ্বর বিশ্বর বিশ্বর বিশ্বর	igi garinang manghananan igi garinang manghananan
SECONOLINA DE CO	. 22 de 1723 de 1725 d	ingularing system report more particular and analysis analysis and analysis analysis and analysis analysis and analysis analysis and analysis analysis and analysis and analysis analysis analysis analy					gan in the emperature paper to the leasing in in	12	grape, las angres en la bress	agent is employed to graph
ùnië.	2102Z 16 NOV 64	Manufacture of the second	<b>3</b>	ECR	L I	2	ale seminal valgaminete, semig en tra el Pitti destination de la Pitti de la P	e con a company de la comp La company de la	and the second of the second	enten en et etalene Kalinario etalen
			7 نننم.	P #4 21	Kin cin		and have a military gramm outigat	- control of the cont	godine, og skalende og trækker fl	ngi estanti

- 1. CAMERA C118 WAS USED IN MISSION C244C FLOWN ON 7 NOVEMBER 1964;
  PROCESSING WAS ACCOMPLISHED IN FIELD.
  - 2. ORIGINAL NEGATIVE:
    - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: RANDOM MINUS DENSITY DOTS ARE PRESENT FOR ABOUT THE FIRST 100 FRAMES OF THE MISSION. WANDERING PLUS DENSITY STREAKS, RUNNING ROUGHLY PARALLEL TO THE INBOARD EDGE, WERE OBSERVED OCCASION—ALLY THROUGHOUT THE MISSION WHERE DENSITY LEVELS PERMITTED DETECTION. MYLAR TAPE PROCESSING SPLICES ARE LOCATED BETWEEN FRAMES 889/900, 1334/1335, AND 2206/2207. A MANUFACTURER'S SPLICE IS LOCATED BETWEEN FRAMES 1109/1110. A STATIC DISCHARGE TRACE AND PRESSURE MARKS ASSOCIATED WITH THE MANUFACTURER'S SPLICE ARE PRESENT ON FRAME 1107. OUTBOARD ROLLER CHATTER BEGINS IN FRAME 1456 AND IS PRESENT INTERMITTENTLY FOR THE REMAINDER OF THE MISSION.

Approved For Release 2002/06/11: CIA-RDP66B00664R000700060023-3

25X1A

3298 (IN 57871)

SECRET

PAGE TWO

- C. 9L SIDE: GHOST IMAGES OF POSITION INDICATORS ARE IMAGED ON ALL FRAMES OF THE MISSION. PLUS DENSITY SPOTS (EYELASHES) ARE PRESENT ON FRAMES 860, 2153, 2177, 2231, 2303, 2369, AND 2436. MYLAR TAPE PROCESSING SPLICES ARE LOCATED BETWEEN FRAMES 880/881, AND 2636/2637. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 1717.
- D. BOTH SIDES: INBOARD ROLLER CHATTER IS PRESENT THROUGHOUT THE MISSION. MINOR EDGE FOG ALONG BOTH EDGES OF BOTH SIDES IS PRESENT INTERMITTENTLY FROM HEAD TO TAIL. A SMALL AREA OF FOG IS PRESENT AT THE OUTBOARD EDGE OF THE FORMAT IN THE VICINITY OF THE VERTICAL INDICATOR DOT LOCATION ON EVERY FRAME OF THE MISSION. UNLESS OTHERWISE INDICATED, ALL FRAME NUMBERS STATED IN THIS REPORT ARE CLOCK COUNTER NUMBERS. THE FIRST TITLED FRAME IS 0000% LAST TITLED FRAME IS 3604.
- E. THERE WERE NO MAJOR PROCESSING ANOMALIES OR CAMERA MAL-FUNCTIONS IN THIS MISSION.
  - 3. POSITIVE:
    - A. PI SUITABILITY IS GOOD.
    - B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS DEGRADE OR OPSCURE APPROXIMATELY 15 PERCENT OF THIS MISSION.

END OF MSG